

June 29, 2016

Project No: RPQ No. 20160203 Drainage Cleaning and Video Inspection Multiple Sites

The above-referenced contract is being considered for small business contract measures. PLEASE NOTE THAT YOUR PARTICIPATION IN THE AVAILABILITY TO BID PROCESS IS VITAL IN ORDER FOR MEASURES TO BE PLACED ON THIS PROJECT. If you are interested in participating as a Small Business Enterprise – Construction (SBE/CONS) firm to perform work in connection with this project and meet the requirements listed in this letter, please complete and return the attached Verification of Availability to Bid by 4:00 PM, FRIDAY, JULY 1, 2016.

The letter of availability may be sent via facsimile transmission to (305) 375-3160 or via email to jescalante@miamidade.gov. If you have any questions, please contact me at (305) 375-3192.

Sincerely,

Jhonnatan Escalante
Capital Improvement Project Analyst

Email: jescalante@miamidade.gov

How can ISD serve you better?
Give us your feedback <u>here!</u>
Connect With Us on Twitter | Facebook | Instagram

VERIFICATION OF AVAILABILITY TO BID

INTERNAL SERVICES DEPARTMENT (ISD) SMALL BUSINESS DEVELOPMENT (SBD) DIVISION COMMUNITY SMALL BUSINESS ENTERPRISE PROGRAM 111 N.W. 1ST STREET, 19th FLOOR

MIAMI, FLORIDA 33128

PHONE: 375-3111 FAX: 375-3160

PROGRAM COORDINATOR: Jhonnatan Escalante

I am herewith submitting this letter of verification of availability and capability to bid, provided the proposed scope of work attached. (**NOTE:** Please provide all the information requested; incomplete and/or incorrect verifications are not acceptable or usable.)

and/or incorrect verifications ar	e not acceptable or u	ısable.)		
CONTRACT TITLE:	Drainage Cleanin	g and Video Insp	oection Multiple Sites	
PROJECT NUMBER:	RPQ No. 20160203 \$200,508.00			
Estimated Contract Amount:				
Scope of work and minimum	requirements for t	his project is att	ached.)	
NAME OF SMALL BUSINES	S ENTERPRISE CO	ONSTRUCTION 1	FIRM (SBE/CONS)	
ADDRESS	CITY		ZIP CODE	
Certification Expires:DATE				
Геlephone:	***Bonding Cap	pacity:		
PRINT NAME AND T	ITLE			
SIGNATURE OF COMPAN	NY REPRESENTAT	TIVE	DATE	
Currently Awarded Projec (Name of Project and Owne	•	Contract Amount	Anticipated Awards	

VERIFICATION OF AVAILABILITY TO BID

CONTRACT TITLE: Drainage Cleaning and Video Inspection Multiple Sites

PROJECT NUMBERS: RPQ No. 20160203

ESTIMATED CONTRACT AMOUNT: \$200,508.00

SCOPE OF WORK:

Drainage Cleaning and Video Inspection Multiple Sites.

Locations:

• NW 7 ST from NW 62 Ave. to NW 65 Ave.

- C-100 Outfall Retrofit between SW 140 ST and SW 152 ST
- Arch Creek Estates
- Biscayne Gardens

Scope of Work:

- A. Work under this Contract includes furnishing of all supervision, labor, materials, tools, equipment and performing all operations required to construct the Work in accordance with the Contract Documents.
- B. Work includes cleaning, video inspection and mapping of the drainage system along those two locations. Work includes, desilting of the pipes and cleaning of the drainage structures, within the projects boundaries that have an ineffective drainage infrastructure. During the desilting of the pipes, the layout of the drainage system is to be mapped on top of recent aerial photos printed on page sizes of eleven inches by seventeen inches (11"x17"). Videotape all desilted drainage pipes to determine diameter, type (solid or perforated) and condition. This information is to be noted on the mapped layout.
- C. If any changes are required due to conflict of design and or field conditions, the Engineer will make the final determination.
- D. The Contractor and all subcontractors, under this Contract, are prohibited from performing any work, other than specified in the Contract and/or directed by the Engineer, within the limits of the project site, without prior written notification to the Engineer. This includes any work for private or commercial entities.

Contract Duration Time: 70 days

Please indicate if you have the resources and equipment for which scope(s) of work your firm can perform by placing a yes or no next to each line item below.

SBE Construction	Yes/No
Pipe Video Inspection and Report	
Desilting Pipe 0 - 48"	
Desilting Drainage Structure	

Contractor Qualifications Questionnaire

questionnaire and forward it completely filled out to this e-mail address: jescalante@miamidade.gov or via fax (305) 375-3160 attention Jhonnatan Escalante.

Proposer (PRIME) has experience completing projects with a similar size and scope as this project, meets the requirements to qualify and can perform the work as required.

Subcontractor (SUB) has experience similar scopes of work and can perform portions of the required work as required.

PRIME/SUB DOES NOT have experience completing projects with similar size and scope as this project and DOES NOT meet the requirements as indicated in the contract.

I certify that to the best of my knowledge all the information provided is verifiable and correct.

COMPANY NAME:

NAME OF REPRESENTATIVE:

SIGNATURE:

SIGNATURE:

This questionnaire will assist SBD in identifying the qualified vendors that "comply" to provide the aforementioned scope of work. Indicate yes "Y" or no "N" on the empty line on the left side of this

PLEASE LIST YOUR FIRMS HISTORY OF SIMILAR PROJECTS, REASON(s) WHY YOUR FIRM DOES NOT MEET THE EXPERIENCE REQUIREMENTS (IF APPLICABLE) AND ANY COMMENTS YOU MAY HAVE ON THE NEXT PAGE

TELEPHONE NUMBER: E-Mail Address: _____

SIMILAR PROJECTS AS PRIME OR SUB-CONTRACTOR

Please list your firm's history of "Projects with Similar Scopes of Services": **Project Title: Client Name:** Contact #: Contract Amount: \$ Scope of Service(s): **Project Title: Client Name:** Contact #: Contract Amount: \$ Scope of Service(s): **Project Title: Client Name:** Contact #: Contract Amount: \$___ Scope of Service(s): **REASONS & COMMENTS**